



We see things because they scatter light. Scatter is quantified in %BRDF+units which is simply scatter power per unit solid angle normalized by the incident power on the sample and the cosine of the scatter angle from surface normal. Most surfaces scatter more near the surface normal.